



Product name	Confidentiality level
B890	Secret
Product version	Total 6 pages
V100R001	

B890 V100R001C259B127SP01 Release Notes

Prepared by **B890** Team
Reviewed by **B890** Team
Granted by **B890** Team

Date 2014-09-25
Date 2014-09-25
Date 2014-09-25



Huawei Technologies Co., Ltd.

All rights reserved



Revision record

Date	Revision Version	Modification Record	Author
2012-11-30	1.00	The first draft	B890 Team
2013-01-18	1.01	The second draft	B890 Team
2013-02-07	1.02	The third draft	B890 Team
2013-03-21	1.03	The fourth draft	B890 Team
2013-9-2	1.15	The fifteenth draft	B890 Team
2013-9-16	1.16	The sixteenth draft	B890 Team
2013-9-30	1.17	The seventeenth draft	B890 Team
2013-10-15	1.18	The eighteenth draft	B890 Team
2013-11-01	1.19	The nineteenth draft	B890 Team
2014-07-09	1.20	The tenth draft	B890 Team
2014-07-25	1.21	The 11th draft	B890 Team
2014-09-25	1.22	The 12th draft	B890 Team



Table of Contents

Software	4
1.1 About This Release	4
1.2 Fixed issues	4
1.2.1 QC issues	4
1.2.2 Major changes in V100R001C259B127SP01	4
1.2.3 Major changes in V100R001C259B126SP02	4
1.2.4 Major changes in V100R001C259B126SP01	5
1.2.5 Major changes in V100R001C259B125SP04	5
1.2.6 Major changes in V100R001C259B125SP03	5
1.2.7 Major changes in V100R001C259B125SP02	5
1.2.8 Major changes in V100R001C259B123	6
1.3 Known Bugs and limitations	6
1.3.1 QC bug	6
1.3.2 Limitations	6



B890 V100R001C259B127SP01 Release Notes

Software

1.1 About This Release

AMSS Version : B890 V100R001C259B120SP02 1281.11.259.07.120SP02

Router Version : B890 V100R001C259B127SP01 1281.11.259.22.127sp01

WEB UI : B890 V100R001C259B127SP01 1281.11.259.22.127sp01

The Release version is for Telus first round test. Click ["About"->" Device Information"](#).

Software version: 1281.11.259.07.120SP02

Router software version: 1281.11.259.22.127sp01

Web UI version: 1281.11.259.22.127sp01

Notes: You should restore the gateway after upgrade

1.2 Fixed issues

1.2.1 QC issues

1.2.2 Major changes in V100R001C259B127SP01

Module	QC ID	Description
SMS Notification		Fixed SMS notify bug
Security Issue		Fixed CSRF、XSS、PING Injection in Web Interface issue.

1.2.3 Major changes in V100R001C259B126SP02

Module	QC ID	Description
SMS Notification		Disable notify when new SMS is received

**1.2.4 Major changes in V100R001C259B126SP01**

Module	QC ID	Description
OpenSSL		Fixed the security issue of OpenSSL, update OpenSSL to 0.9.8za Version.

1.2.5 Major changes in V100R001C259B125SP04

Module	QC ID	Description
Redirect		Fixed the issue of PIN and SIM lock redirect
IPv6		Fixed issue of ping ipv6 not success.

1.2.6 Major changes in V100R001C259B125SP03

Module	QC ID	Description
DDNS		Fixed the issue DDNS update delay
Webui		Fixed some error word

1.2.7 Major changes in V100R001C259B125SP02

Module	QC ID	Description
DDNS		Fixed “Smart Hub sends DDNS update after power cycle” .
DDNS		Add the provider “TELUS” .
SMS notification		Fixed “Time Stamps abbreviation mistake”
Remote management		Support remote management (which is another style of ACL WAN SSL)
Web String		Fixed the wrong string of TELUS.
Quick Setup		Modified as the customer’ s requirement.
Redirect		Fixed” Smart Hub redirects any HTTP request to SMS notification page after SMS notification”



Module	QC ID	Description
Web UI		Modified the “WAN status” style Modified the “System and Network Information” style
Notification		Support Failback notification

1.2.8 Major changes in V100R001C259B123

Module	QC ID	Description
Router		getaddrinfo Cause DNS Crash
WEB UI		String for FOTA
WEB UI		Quick Setup can't work when wifi is off

1.3 Known Bugs and limitations

1.3.1 QC bug

Defect ID	State	Description

1.3.2 Limitations